



CERTIFICATE OF COMPLIANCE

9/12/2024

Contact person: Michael Polansky
Title: Manufacturing Manager
E-mail: mpolansky@muellerelectric.com

Mueller Electric hereby certifies that referenced part number(s) have been evaluated and the materials conform to the European Union's Restriction of Use of Hazardous Substances in Electrical and Electronic Equipment (RoHS) Directive 2002/95/EC, 2011/65/EU (RoHS 2) and (EU)2015/863(RoHS 3). Said products have no intentional addition of:

- Lead (Pb)
- Cadmium (Cd)
- Mercury (Hg)
- Hexavalent Chromium (Cr)
- Polybrominated Biphenyls (PBB)
- Polybrominated Diphenyl (DEHP)
- Bis (2-Ethylhexyl) phthalate (DEHP)
- Benzyl phthalate (BBP)
- Dibutyl phthalate (DBP)
- Di isobutyl phthalate (DIBP)

Any trace impurities of these substances are below the threshold limits as specified by the RoHS directive; specifically, Cr+6, Hg, Pb, PBB, PBDE, DEHP, BBP, DBP and DIBP do not exceed 1000 ppm (0.1%) and Cd does not exceed 100 ppm (0.01%). This declaration is based on our analysis, vendor supplied analysis, material certifications, or laboratory tests of the component materials used in the manufacturing process; however, some of the information is provided without representation or warrant, expressed or implied, regarding accuracy or correctness.

Note. Any part numbers on this sheet ending in -XX(X)-X or some variation of (X) covers all length and or colors of said product.

Mueller Electric Part Number:

| | | | |
|-----------|-------|-------|-------|
| 0440 | 10003 | 10006 | 10009 |
| 2593 (6c) | 10004 | 10007 | 10010 |
| 10002 | 10005 | 10008 | 10011 |

Mueller Electric Company
2850 Gilchrist Rd. Bld 5A
Akron, OH 44305

www.muellerelectric.com

Toll Free: 800.955.2629
Phone: 330.780.2525
Fax: 330.780.2524

| | | | |
|-------|------------|-------------|---------|
| 10012 | 10041 | 80110 (6c) | 1074262 |
| 10013 | 10042 | 80111 (6c) | 1074329 |
| 10014 | 10043 | 80112 | 1078197 |
| 10015 | 10046 | 80113 | 1078199 |
| 10016 | 10047 | 80114 | 1090770 |
| 10017 | 246458 | 80115 | 1090771 |
| 10018 | 247808 | 80116 (6c) | 1095361 |
| 10019 | 247811 | 80117 (6c) | 1099306 |
| 10020 | 306727 | 80118 (6c) | 1101866 |
| 10021 | 80006 (6c) | 80120 | 1107539 |
| 10022 | 80007 (6c) | 130627 | 1107582 |
| 10023 | 80012 (6c) | 235974 | 1107598 |
| 10024 | 80014 (6c) | 240976 | 1107813 |
| 10025 | 80015 (6c) | 245896 | 1107908 |
| 10026 | 80018 (6c) | 247809 | 1602698 |
| 10027 | 80019 (6c) | 341622 | 1602701 |
| 10028 | 80020 (6c) | 347223 | 1602715 |
| 10029 | 80021 (6c) | 347230 | 1604816 |
| 10030 | 80022 (6c) | 759507 | 1604817 |
| 10031 | 80023 (6c) | 775051 | 1604818 |
| 10032 | 80030 | 100000 (6c) | 1605515 |
| 10034 | 80031 | 1033486 | 1605754 |
| 10035 | 80033 | 150042 (6c) | 1606153 |
| 10036 | 80034 | 150045 (6c) | 1606281 |
| 10037 | 80037 (6c) | 1059698 | 1609709 |
| 10038 | 80040 (6c) | 1060683 | 1609874 |
| 10039 | 80108 (6c) | 1064073 | 1609875 |
| 10040 | 80109 (6c) | 1069492 | 1611363 |

| | | | |
|---------|-------------|------------------------|---------------|
| 1611712 | 1622040 | 102-BRAID | AI-000448-XX |
| 1611713 | 1622277 | 163-0004-00 (6c) | AI-000454-XX |
| 1611714 | 1625313 | 163-0006-01 (6c) | AI-000457 |
| 1611715 | 1625358 | 163-0060-01 (6c) | AI-000458 |
| 1611716 | 1625376 | 163-0061-01 (6c) | AI-000461-XX |
| 1612008 | 1625506 | 163-0062-01 (6c) | AI-000462-XX |
| 1612322 | 1625515 | 22.170-.XXM-X | AI-000473 |
| 1612323 | 1625516 | 22.421-.XXM-X | AI-000474-XXX |
| 1612496 | 1625517 | 22.451-.XXM-X | AI-000475 |
| 1612629 | 180000 | 458-3 | AI-000476 |
| 1612642 | 180001 | 7790207 | AI-000480 |
| 1612920 | 400003 (6c) | 949-1 | AI-000483 |
| 1614599 | 1010362 | AI-21.060-1M | AI-000701 |
| 1616057 | 1023695 | AI-000151-XX (6c) | AI-000918-X |
| 1616058 | 1034207 | AI-000210 (6c) | AI-000500-XX |
| 1616059 | 1050040 | AI-000210S (6c) | AI-000501-XXX |
| 1616060 | 1080950 | AI-000210T (6c) | AI-000503E-XX |
| 1616061 | 1106756 | AI-000374-X | AI-000504-XX |
| 1616062 | 1107532 | AI-000374-2 | AI-000505-XX |
| 1616063 | 1107535 | AI-000404-XX(X)-X (6c) | AI-20167 |
| 1617853 | 1600745 | AI-000406-X (6c) | AI-20167N |
| 1618164 | 1602869 | AI-000407-5 | AI-20184 |
| 1619012 | 1605376 | AI-000408-0/2 (6c) | AI-20315 |
| 1619206 | 1605823 | AI-000422 | AI-50020N |
| 1620633 | 1605943 | AI-000431 (6c) | AI-50030N |
| 1621930 | 1605982 | AI-000433 | AI-50040N |
| 1622038 | 1620758 | AI-000441 | AI-50041N |
| 1622039 | 1622068 | AI-000443 | AI-50042N |

| | | | |
|-----------|-----------------|------------------------|------------------------|
| AI-50043N | AI-50213 | BU-00247-X (6c) | BU-108K-X |
| AI-50050N | AI-50220N | BU-00249-X (6c) | BU-109-X |
| AI-50060N | AI-50230N | BU-00260 (6c) | BU-110-X |
| AI-50070N | AI-50240N | BU-00262-X (6c) | BU-111-X |
| AI-50086N | AI-50250N | BU-00282-X | BU-1111-A-XX(X)-X (6c) |
| AI-50090N | AI-50260N | BU-00283 | BU-111STG-X |
| AI-50100N | AI-50270N | BU-00285 | BU-112-X |
| AI-50101N | AI-50280N | BU-00286 | BU-1120-A-XX(X)-X (6c) |
| AI-50102N | AI-50290N | BU-00287 | BU-1125-A-XX(X)-X (6c) |
| AI-50103N | AI-70206 | BU-0030-A-XX(X)-X | BU-1149-A-XX(X)-X (6c) |
| AI-50140N | AI-70207 | BU-0050-B-XX(X)-X (6c) | BU-113APN |
| AI-50150N | AI-70208 | BU-0050-I-XX(X)-X (6c) | BU-113XPN LARGE |
| AI-50160N | AI-70209 | BU-0061-M-XX(X)-X (6c) | BU-114-X |
| AI-50176N | AI-70212 | BU-0070-B-XX(X)-X (6c) | BU-115-X |
| AI-50177N | AI-70213 | | BU-1150-C-XX(X)-X (6c) |
| AI-50180N | AI-70315 | BU-0070-F-XX(X)-X (6c) | BU-1153-F-XX(X)-X (6c) |
| AI-50181N | BU-00201-X (6c) | BU-X90135S (6c) | BU-1153-F-XX(X)-X (6c) |
| AI-50186N | BU-00202-X (6c) | BU-1010-A-XX(X)-X (6c) | BU-1156-C-XX(X)-X (6c) |
| AI-50187N | BU-00207-X (6c) | BU-1010-N-XX(X)-X (6c) | BU-1161-M-XX(X)-X (6c) |
| AI-50192N | BU-00208-X (6c) | BU-1020-A-XX(X)-X(6c) | BU-1162-R-XX(X)-X (6c) |
| AI-50195N | BU-00211-X (6c) | BU-1031-A-XX(X)-X (6c) | BU-1161-N-XX(X)-X (6c) |
| AI-50197N | BU-00225-X (6c) | BU-1050-C-XX(X)-X (6c) | BU-1170-C-XX(X)-X (6c) |
| AI-50198N | BU-00232 (6c) | BU-1080-E-XX(X)-X (6c) | BU-1170-F-XX(X)-X (6c) |
| AI-50206 | BU-00233-X (6c) | BU-102B-X | BU-5111-A-XX(X)-X (6c) |
| AI-50207 | BU-00241 (6c) | BU-102BK | BU-P6249-XX(X)-X (6c) |
| AI-50208 | BU-00243-X (6c) | BU-102W-X | BU-116K |
| AI-50209 | BU-00245-X (6c) | BU-103TX | BU-117-X |
| AI-50212 | BU-00246-X (6c) | BU-103X | BU-118 |

| | | | |
|-------------------|---------------|---------------|------------------------|
| BU-119 | BU-12ZS32-PG9 | BU-12ZU04-PG9 | BU-12ZS31-PG7 |
| BU-11APN | BU-12ZS33-PG7 | BU-12ZU05-PG7 | BU-13-X |
| BU-11APN-G13Z | BU-12ZS33-PG9 | BU-12ZU05-PG9 | BU-1402551 (6c) |
| BU-11APN-HZZZ | BU-12ZS34-PG7 | BU-12ZU06-PG7 | BU-1404940 (6c) |
| BU-11APN-JZZZ | BU-12ZS34-PG9 | BU-12ZU06-PG9 | BU-1406105 (6c) |
| BU-11APS | BU-12ZS35-PG7 | BU-12ZU21-PG7 | BU-1414-E-XX(X)-X (6c) |
| BU-11APS-G13Z | BU-12ZS35-PG9 | BU-12ZU21-PG9 | BU-1420-A-XX(X)-X (6c) |
| BU-11APS-HZZZ | BU-12ZS36-PG7 | BU-12ZU22-PG7 | BU-1420701201 (6c) |
| BU-11CPN | BU-12ZS36-PG9 | BU-12ZU22-PG9 | BU-1420701206 (6c) |
| BU-11CPN-G23Z | BU-12ZS41-PG7 | BU-12ZU23-PG7 | BU-1420701211 (6c) |
| BU-11CPS | BU-12ZS41-PG9 | BU-12ZU23-PG9 | BU-1420701216 (6c) |
| BU-11CPS-G23Z | BU-12ZS42-PG7 | BU-12ZU24-PG7 | BU-1420701231 (6c) |
| BU-11XPN | BU-12ZS42-PG9 | BU-12ZU24-PG9 | BU-1420701236 (6c) |
| BU-120 | BU-12ZS43-PG7 | BU-12ZU25-PG7 | BU-1420701301 (6c) |
| BU-121-X | BU-12ZS43-PG9 | BU-12ZU25-PG9 | BU-1420701306 (6c) |
| BU-122 | BU-12ZS44-PG7 | BU-12ZU26-PG7 | BU-1420701321 (6c) |
| BU-122730291 (6c) | BU-12ZS44-PG9 | BU-12ZU26-PG9 | BU-1420701406 (6c) |
| BU-122730424 (6c) | BU-12ZS45-PG7 | BU-8ZU01 | BU-1420701411 (6c) |
| BU-123 | BU-12ZS45-PG9 | BU-8ZU02 | BU-1420701421 (6c) |
| BU-124 | BU-12ZS46-PG7 | BU-8ZU03 | BU-1420701491 (6c) |
| BU-125 | BU-12ZS46-PG9 | BU-8ZU04 | BU-1420701501 (6c) |
| BU-126-X | BU-12ZU01-PG7 | BU-8ZU05 | BU-1420701502 (6c) |
| BU-127-X | BU-12ZU01-PG9 | BU-8ZU06 | BU-1420701506 (6c) |
| BU-128-X | BU-12ZU02-PG7 | BU-8ZU07 | BU-1420701507 (6c) |
| BU-165-F | BU-12ZU02-PG9 | BU-8ZU08 | BU-1420701551 (6c) |
| BU-12ZS31-PG7 | BU-12ZU03-PG7 | BU-8ZU10 | BU-1420701556 (6c) |
| BU-12ZS31-PG9 | BU-12ZU03-PG9 | BU-8ZU11 | BU-1420701621 (6c) |
| BU-12ZS32-PG7 | BU-12ZU04-PG7 | BU-8ZU12 | BU-1420701631 (6c) |

| | | | |
|--------------------|------------------------|--------------|--------------|
| BU-1420701636 (6c) | BU-1420761861 (6c) | BU-190170047 | BU-190700153 |
| BU-1420701801 (6c) | BU-1420761871 (6c) | BU-190230003 | BU-191420003 |
| BU-1420701806 (6c) | BU-1420761881 (6c) | BU-190230005 | BU-191420005 |
| BU-1420701841 (6c) | BU-1420761891 (6c) | BU-190230008 | BU-191420007 |
| BU-1420701851 (6c) | BU-1420771821 (6c) | BU-190230010 | BU-191440015 |
| BU-1420701871 (6c) | BU-1420771831 (6c) | BU-190230012 | BU-191440020 |
| BU-1420701873 (6c) | BU-1420801811 (6c) | BU-190340005 | BU-191440026 |
| BU-1420711201 (6c) | BU-1421-A-XX(X)-X (6c) | BU-190340009 | BU-191440037 |
| BU-1420711202 (6c) | BU-1450-C-XX(X)-X (6c) | BU-190380004 | BU-191440039 |
| BU-1420711271 (6c) | BU-16-X (6c) | BU-190380006 | BU-191440042 |
| BU-1420711281 (6c) | BU-1669848 (6c) | BU-190380007 | BU-191540004 |
| BU-1420711301 (6c) | BU-1682935 (6c) | BU-190380009 | BU-191540015 |
| BU-1420711521 (6c) | BU-190030001 | BU-190540035 | BU-191540022 |
| BU-1420711811 (6c) | BU-190030040 | BU-190540039 | BU-191540028 |
| BU-1420711821 (6c) | BU-190040001 | BU-190540042 | BU-191540035 |
| BU-1420711841 (6c) | BU-190040005 | BU-190540044 | BU-191640003 |
| BU-1420711881 (6c) | BU-19005-0001 | BU-190540048 | BU-191640007 |
| BU-1420721841 (6c) | BU-19005-005 | BU-190540054 | BU-191640008 |
| BU-1420761861 (6c) | BU-190070001 | BU-190540075 | BU-191640013 |
| BU-1420721871 (6c) | BU-190070021 | BU-190540086 | BU-191640026 |
| BU-1420721881 (6c) | BU-190070040 | BU-190540088 | BU-191640029 |
| BU-1420721882 (6c) | BU-190110035 | BU-190540108 | BU-191640030 |
| BU-1420761801 (6c) | BU-190110037 | BU-190540110 | BU-191640033 |
| BU-1420761811 (6c) | BU-190110039 | BU-190540113 | BU-191640034 |
| BU-1420761821 (6c) | BU-190170007 | BU-190700121 | BU-191640043 |
| BU-1420761831 (6c) | BU-190170014 | BU-190700123 | BU-191640044 |
| BU-1420761841 (6c) | BU-190170031 | BU-190700132 | BU-191640056 |
| BU-1420761851 (6c) | BU-190170037 | BU-190700136 | BU-191640063 |

| | | | |
|--------------|---------------------------|-------------------------|------------------------|
| BU-191640066 | BU-2020-A-XX(X)-X (6c) | BU-21MPS | BU-25X |
| BU-191640071 | BU-2020SR-A-XX(X)-X | BU-21XPN | BU-26-X |
| BU-191640077 | BU-2030-A-XX(X)-X (6c) | BU-21XPS | BU-26101-X (6c) |
| BU-191640085 | BU-2031-A-XX(X)-X (6c) | BU-2241-D-XX(X)-X (6c) | BU-26106-X (6c) |
| BU-191640086 | BU-20431-X (6c) | BU-2243-D-XX(X)-X (6c) | BU-26130-X (6c) |
| BU-191930014 | BU-20432-X (6c) | BU-22731031 (6c) | BU-2626-N-XX(X)-X |
| BU-191930016 | BU-20433-X (6c) | BU-23-X | BU-2641-D-XX(X)-X (6c) |
| BU-191930021 | BU-2044-A-XX(X)-X (6c) | BU-2323-10-XX(X)-X (6c) | BU-2643-D-XX(X)-X (6c) |
| BU-191930023 | BU-21349300405010 (6c) | BU-24APN | BU-27 |
| BU-191930055 | BU-2141-D-XX(X)-X (6c) | BU-24APN-B13Z | BU-27-B1ZB |
| BU-191930074 | BU-21AEZ | BU-24APN-BZZZ | BU-27-B4ZZ |
| BU-191930080 | BU-21APN | BU-24APN-DZZZ | BU-27-B5ZZ |
| BU-191930082 | BU-21APN-D13Z | BU-24APN-E13Z | BU-27-BZZM |
| BU-191930106 | BU-21APN-E13Z | BU-24APS | BU-27-BZZZ |
| BU-191930109 | BU-21APN-N13Z | BU-24APS-B13Z | BU-27C |
| BU-191930116 | BU-21APS | BU-24APS-DZZZ | BU-27C-B23Z |
| BU-191930120 | BU-21APS-E13Z | BU-24APS-E13Z | BU-27C-DZZZ |
| BU-191930137 | BU-21APS-N13Z | BU-24CPN-BZZZ | BU-27C-EZZ |
| BU-191930199 | BU-21CEZ | BU-24CPN-EZZZ | BU-27C-EZZZ |
| BU-192020019 | BU-21CPN | BU-25 | BU-27CG |
| BU-192020039 | BU-21CPN-DZZZ | BU-25-B13Z | BU-27CG-B23Z |
| BU-192020063 | BU-21CPN-GZZZ | BU-25C | BU-27CGW |
| BU-192120001 | BU-21CPN-H23Z | BU-25C-B23Z | BU-27CGW-B23Z |
| BU-192120003 | BU-21CPN-H23Z | BU-25C-DZZZ | BU-27C-Z1WZ |
| BU-192120005 | BU-21CPN-JZZZ | BU-25C-E2ZZ | BU-27C-ZZ8Z |
| BU-192150009 | BU-21CPS | BU-25C-EZZZ | BU-27-EZZZ |
| BU-192150022 | BU-21CPS-GZZZ | BU-25-DZZZ | BU-27F-ZZZZ |
| BU-192150028 | BU-21MPN | BU-25-E12Z | BU-27-KZZZ |

Mueller Electric Company
2850 Gilchrist Rd. Bld 5A
Akron, OH 44305

www.muellerelectric.com

Toll Free: 800.955.2629
Phone: 330.780.2525
Fax: 330.780.2524

| | | | |
|--------------------------|----------------------|------------------------------|--------------------|
| BU-27M | BU-31104-0 (6c) | BU-4061-C-- XX(X)--X (6c) | BU-4150029006 (6c) |
| BU-27-MZZZ | BU-3110410-X (6c) | | BU-4150029012 (6c) |
| BU-27X | BU-31104-2 (6c) | BU-4062-C-- XX(X)--X (6c) | BU-4150029018 |
| BU-27-Z1ZA | BU-3131-A- XX(X)--X | BU-40A-X | BU-4150029024 (6c) |
| BU-27-Z1ZB | BU-3131-D-- XX(X)--X | BU-40C | BU-4150029036 (6c) |
| BU-2741-D-XX(X)-X (6c) | BU-3149-A-8-X | BU-40C-X | BU-4150029048 (6c) |
| BU-28-X | BU-31602-X (6c) | BU-4150003006 (6c) | BU-4150029M2.0 |
| BU-29-X | BU-31603-X (6c) | BU-4150003012 (6c) | BU-4150029M3.0 |
| BU-2929-M-XX(X)-X (6c) | BU-31604-X (6c) | BU-4150003018 (6c) | BU-4150029MM150 |
| BU-29-X | BU-31605-X (6c) | BU-4150003024 (6c) | BU-4150029MM250 |
| BU-29-A | BU-31607-X (6c) | BU-4150003036 (6c) | BU-4150029MM500 |
| BU-30 | BU-31610-X (6c) | BU-4150003M1.0 (6c) | BU-4150029MM750 |
| BU-30211A-X | BU-31610X-X (6c) | BU-4150003MM500 (6c) | BU-4150030006 |
| BU-3030-A-XX(X)-X | BU-32-X | | BU-4150030012 |
| BU-3030-D-XX(X)-X | BU-32101-X (6c) | BU-4150003MM750 (6c) | BU-4150030024 |
| BU-3030-N-XX(X)-X | BU-32601-X (6c) | BU-4150028006 (6c) | BU-4150030036 |
| BU-3031-A-XX(X)-X | BU-32614-0 (6c) | BU-4150028012 (6c) | BU-4150030048 |
| BU-3044-A-XX(X)-X (6c) | BU-3261410-X (6c) | BU-4150028018 | BU-4150030M1.5 |
| BU-3070-C- XX(X)--X (6c) | BU-32614-X (6c) | BU-4150028024 (6c) | BU-4150030MM150 |
| BU-30BL | BU-32616-X (6c) | BU-4150028036 (6c) | BU-4150030MM250 |
| BU-30C | BU-33C | BU-4150028048 (6c) | BU-4150030MM500 |
| BU-30G | BU-33C-H13Z | BU-4150028M1.0 | BU-4150031006 |
| BU-30TBO | BU-34 | BU-4150028M1.5 | BU-4150031012 |
| BU-30TBO-ZZZT | BU-34C | BU-4150028M2.0 | BU-4150031018 |
| BU-30X | BU-34M | BU-4150028MM150 | BU-4150031024 |
| BU-30XA | BU-34X | BU-4150028MM250 | BU-4150031036 |
| BU-30XTBO | BU-35-X | BU-4150028MM500 | BU-4150031048 |
| BU-31-X | BU-36-X | BU-4150028MM750 | BU-4150031M1.0 |

| | | | |
|----------------------|----------------------|--------------------|------------------------|
| BU-4150031M1.5 | BU-4150059M1.5 (6c) | BU-4150088200 (6c) | BU-42-X |
| BU-4150031MM150 | BU-4150059MM250 (6c) | BU-4150088250 (6c) | BU-42PR-X |
| BU-4150031MM250 | BU-4150059MM500 (6c) | BU-4150088300 (6c) | BU-43-X |
| BU-4150031MM500 | BU-4150059MM750 (6c) | BU-4150088500 (6c) | BU-43PR-X |
| BU-4150031MM750 | BU-4150061012 (6c) | BU-41A-X | BU-43S-X |
| BU-4150032006 | BU-4150061024 (6c) | BU-41APN | BU-43SPR-X |
| BU-4150032012 | BU-4150061036 (6c) | BU-41APN-RZZZ | BU-4444-A-XX(X)-X (6c) |
| BU-4150032018 | BU-4150061060 (6c) | BU-41APN-RZZZ-X | BU-45 |
| BU-4150032024 | BU-4150074006 | BU-41APN-SZZZ | BU-45-BZ5Z |
| BU-4150032036 | BU-4150074012 | BU-41APN-SZZZ-0 | BU-45-BZZZ |
| BU-4150032048 | BU-4150074024 | BU-41APN-Z4ZZ | BU-45C |
| BU-4150032M1.5 | BU-4150081003 (6c) | BU-41APS | BU-45C-B24Z |
| BU-4150032MM250 | BU-4150081004 (6c) | BU-41APS-RZZZ | BU-45C-EZZZ |
| BU-4150038012 (6c) | BU-4150081005 (6c) | BU-41APS-SZZZ | BU-45-DZZZ |
| BU-4150038024 (6c) | BU-4150081006 (6c) | BU-41APS-SZZZ-2 | BU-45-EZZZ |
| BU-4150038036 (6c) | BU-4150081007 (6c) | BU-41C-X | BU-45-ZZ5Z |
| BU-4150038048 (6c) | BU-4150081008 (6c) | BU-41CPN | BU-46-X-X |
| BU-4150038060 (6c) | BU-4150081012 (6c) | BU-41CPN-0Z8Z | BU-46-X-XL |
| BU-4150038M1.0 (6c) | BU-4150081018 (6c) | BU-41CPN-RZZZ | BU-46A-X |
| BU-4150038M2.0 (6c) | BU-4150081024 (6c) | BU-41CPN-SZZZ | BU-46A-033Z |
| BU-4150038MM250 (6c) | BU-4150081MM150 (6c) | BU-41CPN-VZZZ | BU-46A-XL |
| BU-4150038MM500 (6c) | BU-4150081MM750 (6c) | BU-41CPN-VZZZ-X | BU-46A-0YZX |
| BU-4150059012 (6c) | BU-4150088050 (6c) | BU-41CPS | BU-46A-6ZZZA |
| BU-4150059024 (6c) | BU-4150088100 (6c) | BU-41CPS-0Z8Z | BU-46APN |
| BU-4150059036 (6c) | BU-4150088150 (6c) | BU-41CPS-RZZZ | BU-46APS |
| BU-4150059048 (6c) | | BU-41CPS-SZZZ | BU-46A-R4ZX |
| BU-4150059060 (6c) | | BU-41CPS-VZZZ | BU-46A-Z1ZZ |
| | | BU-41CPS-VZZZ-2 | BU-46A-Z4ZZ |

| | | | |
|-------------|------------------------|-----------------|---------------------------|
| BU-46C-X | BU-49-X | BU-60 | BU-60PR-2.077 |
| BU-46C-023Z | BU-5030-C-XX(X)-X (6c) | BU-60-7ZZN | BU-60PR-2.090 |
| BU-46C-XL | BU-5031-C-XX(X)-X (6c) | BU-60C | BU-60PR2+BU62-2 |
| BU-46C-G13Z | BU-5050-B-XX(X)-X (6c) | BU-60CBS-DZZZ | BU-60S |
| BU-46CPN | BU-5070-B-XX(X)-X (6c) | BU-60CH-X | BU-60SCAP |
| BU-46M-X | BU-50C | BU-60CHS-X | BU-60S-ZZZX |
| BU-46M-023Z | BU-50C-B21Z | BU-60CPR-1 | BU-60TBO |
| BU-46PR-X | BU-50C-B4ZZ | BU-60CPR-2 | BU-60TBO-X |
| BU-46PR-XL | BU-50C-DZZZ | BU-60CS | BU-60TBO-A |
| BU-46PR-5 | BU-50C-EZZZ | BU-60CSLOW | BU-60TBOM3 |
| BU-46X | BU-50C-IZZZ | BU-60CSS | BU-60TBO-ZZ1Z |
| BU-46X-2 | BU-5100-A-XX(X)-X (6c) | BU-60CS-ZZZX | BU-60U |
| BU-46X-ZZZX | BU-5110-A-4-0 (6c) | BU-60CX | BU-60X |
| BU-47-X | BU-5120-A-4-0 (6c) | BU-60C-ZZZN | BU-60X-BLACK |
| BU-48B | BU-5131-A-4-0 (6c) | BU-60C-ZZZX | BU-60XTBO |
| BU-48B2E | BU-5144-A-4-0 (6c) | BU-60-EZZZ | BU-60XTBOS |
| BU-48B-B4ZZ | BU-51C | BU-60G | BU-60-ZZZJ |
| BU-48B-BZZZ | BU-51C-2 | BU-60H-X | BU-60-ZZZK |
| BU-48B-D11Z | BU-51C-B21Z | BU-60HPB-Z7ZZ-X | BU-60-ZZZN |
| BU-48B-EZZZ | BU-5200-A-4-0 (6c) | BU-60HPR-.077-X | BU-60-ZZZX |
| BU-48BX | BU-5210-A-4-0 (6c) | BU-60HPR-X | BU-61 |
| BU-48B-ZZLZ | BU-5231-A-4-0 (6c) | BU-60HPR2-1-X | BU-6161-M-XX(X)-X (6c) |
| BU-48C | BU-5244-A-4-0 (6c) | BU-60HS-X | BU-6161MG-XX(X)-X (6c) |
| BU-48C-B21Z | BU-55 | BU-60M | BU-6161-N-XX(X)-X (6c) |
| BU-48C-B24Z | BU-55-B11Z | BU-60-MRZ-WS | BU-6162-M-XX(X)-X (6c) |
| BU-48C-DZZZ | BU-55-M0ZZ | BU-60PB | BU-6162-M-XX(X)-X (6c) |
| BU-48C-EZZZ | BU-58 | BU-60PR-.093 | BU-6162-M-XX(X)-X (6c) |
| BU-48C-SJM | BU-58-DZZZ | BU-60PR2 | BU-62-X |
| | | | BU-62-A |

Mueller Electric Company
2850 Gilchrist Rd. Bld 5A
Akron, OH 44305

www.muellerelectric.com

Toll Free: 800.955.2629
Phone: 330.780.2525
Fax: 330.780.2524

| | | | |
|------------------------|------------------------|-----------------------|------------------------|
| BU-62S-X | BU-90-X | BU-P1081 | BU-P3690-X (6c) |
| BU-63-X | BU-9310-A-XX(X)-X (6c) | BU-P1166-XX(X)-X (6c) | BU-P3750-X (6c) |
| BU-6363-M-XX(X)-X | BU-9410-A-XX(X)-X (6c) | BU-P122505-X (6c) | BU-P3760-X (6c) |
| BU-63C-X | BU-95 | BU-P1269 (6c) | BU-P3770-X (6c) |
| BU-63X-X | BU-95-B0ZZ | BU-P1270 (6c) | BU-P3778 |
| BU-65-X | BU-95-BZZZ | BU-P1296 (6c) | BU-P3781-XX(X)-X (6c) |
| BU-65-0/2 | BU-95-D11Z | BU-P1330-X (6c) | BU-P3782-XX(X)-X (6c) |
| BU-651-X | BU-95-EZZZ | BU-P1809-X (6c) | BU-P3791 (6c) |
| BU-652-X | BU-95-M0ZZ | BU-P1825-X (6c) | BU-P3839 (6c) |
| BU-70 | BU-95-MZZZ | BU-P2035-X (6c) | BU-P3839-3 (6c) |
| BU-7042-F-XX(X)-X | BU-L0000-375 | BU-P2142-X (6c) | BU-P3846 (6c) |
| BU-7070-B-XX(X)-X (6c) | BU-L0000-375TIN | BU-P2143-X (6c) | BU-P3925-X (6c) |
| BU-7070-F-XX(X)-X (6c) | BU-L0000-500TIN | BU-P2240-X (6c) | BU-P4115 (6c) |
| BU-70C | BU-L000-500TIN | BU-P2249-C-XX(X) (6c) | BU-P4160 (6c) |
| BU-70CS | BU-L00-375 | BU-P2269 (6c) | BU-P4243 (6c) |
| BU-70S | BU-L00-375TIN | BU-P2854-X (6c) | BU-P4289 (6c) |
| BU-72-X | BU-L00-500TIN | BU-P2945-X (6c) | BU-P4290 (6c) |
| BU-74-X | BU-L0-250TIN | BU-P3264 (6c) | BU-P4290-NS (6c) |
| BU-75K | BU-L0-375 | BU-P3267 (6c) | BU-P4513 (6c) |
| BU-78K | BU-L0-375TIN | BU-P3276 (6c) | BU-P4543-X (6c) |
| BU-85 | BU-L0-500TIN | BU-P3277 (6c) | BU-P4578 (6c) |
| BU-85-B11Z | BU-L1-375TIN | BU-P3283 (6c) | BU-P4911B-XX(X)-X (6c) |
| BU-85C | BU-L2-313 | BU-P3285 (6c) | BU-P4969 (6c) |
| BU-85C-B24Z | BU-L4-313TIN | BU-P3452 (6c) | BU-P4970 (6c) |
| BU-85-DZZZ | BU-L4-375TIN | BU-P3452-NS (6c) | BU-P5145 (6c) |
| BU-85-EZZZ | BU-L6-250 | BU-P3533 (6c) | BU-P5167-X (6c) |
| BU-85-MZZZ | BU-L6-313TIN | BU-P3534 (6c) | BU-P5168-X (6c) |
| BU-87-X | BU-L8-375TIN | BU-P3542-X (6c) | BU-P5169-X (6c) |

| | | | |
|---------------------------------|----------------|-----------------|-----------------|
| BU-P5170-X (6c) | C3ACXX(F/M)XXX | C5ACXX(F/M)XXX | C84ACXX(F/M)XXX |
| BU-P5319 (6c) | C3ADXX(F/M)XXX | C5ADXX(F/M)XXX | C84ADXX(F/M)XXX |
| BU-P5519A | C3BXX(F/M)XXX | C5BXX(F/M)XXX | C84BXX(F/M)XXX |
| BU-P5697-XX(X) (6c) | C3BBXX(F/M)XXX | C5BBXX(F/M)XXX | C84BBXX(F/M)XXX |
| BU-P6567 | C3BCXX(F/M)XXX | C5BCXX(F/M)XXX | C84BCXX(F/M)XXX |
| BU-P6713 (6c) | C3BDXX(F/M)XXX | C5BDXX(F/M)XXX | C84BDXX(F/M)XXX |
| BU-P6738 (6c) | C3CXX(F/M)XXX | C5CXX(F/M)XXX | C84CXX(F/M)XXX |
| BU-P6883 (6c) | C3CCXX(F/M)XXX | C5CCXX(F/M)XXX | C84CCXX(F/M)XXX |
| BU-P72913-X (6c) | C3CDXX(F/M)XXX | C5CDXX(F/M)XXX | C84CDXX(F/M)XXX |
| BU-P72914-X | C3DXX(F/M)XXX | C5DXX(F/M)XXX | C84DXX(F/M)XXX |
| BU-P72918 (6c) | C3DDXX(F/M)XXX | C5DDXX(F/M)XXX | C84DDXX(F/M)XXX |
| BU-P72930-X (6c) | C4AXX(F/M)XXX | C83AXXMXXX | C85AXXMXXX |
| BU-P72973 (6c) | C4AAXX(F/M)XXX | C83AAXX(F/M)XXX | C85AAXX(F/M)XXX |
| BU-PB12-X (6c) | C4ABXX(F/M)XXX | C83ABXX(F/M)XXX | C85ABXX(F/M)XXX |
| BU-PB18-X (6c) | C4ACXX(F/M)XXX | C83ACXX(F/M)XXX | C85ACXX(F/M)XXX |
| BU-PB24-X (6c) | C4ADXX(F/M)XXX | C83ADXX(F/M)XXX | C85ADXX(F/M)XXX |
| BU-PB36-X (6c) | C4BXX(F/M)XXX | C83BXX(F/M)XXX | C85BXX(F/M)XXX |
| BU-PB4-X (6c) | C4BBXX(F/M)XXX | C83BBXX(F/M)XXX | C85BBXX(F/M)XXX |
| BU-PB48-X (6c) | C4BCXX(F/M)XXX | C83BCXX(F/M)XXX | C85BCXX(F/M)XXX |
| BU-PB60-X (6c) | C4BDXX(F/M)XXX | C83BDXX(F/M)XXX | C85BDXX(F/M)XXX |
| BU-PB72-X (6c) | C4CXX(F/M)XXX | C83CXX(F/M)XXX | C85CXX(F/M)XXX |
| BU-PMDP-X (6c) | C4CCXX(F/M)XXX | C83CCXX(F/M)XXX | C85CCXX(F/M)XXX |
| BU-PMDP-S-X (6c) | C4CDXX(F/M)XXX | C83CDXX(F/M)XXX | C85CDXX(F/M)XXX |
| BU-X15400-X | C4DXX(F/M)XXX | C83DXX(F/M)XXX | C85DXX(F/M)XXX |
| BU-T4171110405002- 0.2M (6c) | C4DDXX(F/M)XXX | C83DDXX(F/M)XXX | C85DDXX(F/M)XXX |
| C3AXX(F/M)XXX | C5AXX(F/M)XXX | C84AXXMXXX | CA-130A |
| C3AAXX(F/M)XXX | C5AAXX(F/M)XXX | C84AAXX(F/M)XXX | CA-19-3 |
| C3ABXX(F/M)XXX | C5ABXX(F/M)XXX | C84ABXX(F/M)XXX | CC-000168 |

Mueller Electric Company
2850 Gilchrist Rd. Bld 5A
Akron, OH 44305

www.muellerelectric.com

Toll Free: 800.955.2629
Phone: 330.780.2525
Fax: 330.780.2524

| | | | |
|-----------------|------------------------|------------------|---------------------|
| CC-000180 | CL5CX(F/M)XXX | KE-CA-130B | TL-0304 (6c) |
| CL4AXXMXXX | CL5CCXX(F/M)XXX | KE-KT-CA22 | TL-308 (6c) |
| CL4AAXX(F/M)XXX | CL5CDXX(F/M)XXX | KE-KT-CA23 | TL-0312 (6c) |
| CL4ABXX(F/M)XXX | CL5DXX(F/M)XXX | KE-KT-X90266 | TL-312 (6c) |
| CL4ACXX(F/M)XXX | CL5DDXX(F/M)XXX | KE-PG-X90070 | TL-0318 (6c) |
| CL4ADXX(F/M)XXX | JP-25182 | KE-V-6517-RH-30 | TL-0320 (6c) |
| CL4BXX(F/M)XXX | JP-25182-S | KE-X90070 | TL-0050 (6c) |
| CL4BBXX(F/M)XXX | JP-33674 | KE-X90081-08 | TL-250 (6c) |
| CL4BCXX(F/M)XXX | JP-33699 | KE-X90081-13 | TL-0044 (6c) |
| CL4BDXX(F/M)XXX | JP-342677 | KT-1261 | TL-E4-20431 (6c) |
| CL4CXX(F/M)XXX | JP-8681-X | KT-BMMPS | TL-E1-26130 (6c) |
| CL4CCXX(F/M)XXX | JP-8681-BX | KT-MMPS | TL-31605-340 (6c) |
| CL4CDXX(F/M)XXX | JP-8783-J | KT-MS001 | X000911-C-48-0 (6c) |
| CL4DXX(F/M)XXX | JP-8783-L | MKP CABLE (6c) | X90249 (6c) |
| CL4DDXX(F/M)XXX | JP-8783-TJ | MKP-CABLE (6c) | X90289 (6c) |
| CL5AXXMXXX | KE-5050-B-XX(X)-X (6c) | SMAF-MMCXM31605 | X90290 (6c) |
| CL5AAXX(F/M)XXX | KE-7070-B-60-0 | SMBM-BNCM17405 | WI-M-10-XX(X)-X |
| CL5ABXX(F/M)XXX | KE-7171-B-48-0 | SMBM-BNCM17410 | WI-M-14-XX(X)-X |
| CL5ACXX(F/M)XXX | KE-BU-30C | SMBM-SMBM17403 | WI-M-18-XX(X)-X |
| CL5ADXX(F/M)XXX | KE-BU-32-X | SMBM-SMBM17405 | WI-M-20-XX(X)-X |
| CL5BXX(F/M)XXX | KE-BU-60 | SMBM-SMBM17410 | WI-M-8-XX(X)-X |
| CL5BBXX(F/M)XXX | KE-BU-62-X | SPADE 30212 (6c) | |
| CL5BCXX(F/M)XXX | KE-CA-107B | TL-0070 (6c) | |
| CL5BDXX(F/M)XXX | KE-CA-109A | TL-0071 (6c) | |

Michael Polansky

Mueller Electric, Manufacturing Manager

Michael Polansky

Mueller Electric Company
2850 Gilchrist Rd. Bld 5A
Akron, OH 44305

www.muellerelectric.com

Toll Free: 800.955.2629
Phone: 330.780.2525
Fax: 330.780.2524